


# Demand the Best

# MAHLE

## Ford 6.0L Power Stroke® Standpipe rebuild gasket kit

Replacing a failed standpipe on a 6.0L Power Stroke engine? No need to purchase the complete standpipe! The MAHLE gasket kit includes all of the o-rings required to rebuild one standpipe assembly and front port plug – regardless if it is a one or two-piece configuration and new or old style!

### MAHLE Set (13 pcs.)




MAHLE part # GS33998 includes: crankcase (CCV) tube o-ring, ICP sensor o-ring, HPOP discharge tube o-ring (for 03-04 models), port plug d-rings, standpipe d-rings (14MM, 17MM, 19MM), standpipe and port plug split seals (large & small), and rail plug o-ring

GS33998 is applicable for Ford 363 cid (6.0L) OHV 32v V8 Power Stroke diesel, model years 2003-2010.

**TIP** Two (2) standpipe rebuild kits are required per engine. When replacing a head gasket, it is suggested to inspect the standpipe seals.

### Competitor Set (9 pcs.)



Competitor part DOES NOT INCLUDE: crankcase (CCV) tube o-ring, ICP sensor o-ring, HPOP discharge tube o-ring (for 03-04 models), and rail plug o-ring

## OE replacement standpipe

The OEM only offers the complete standpipe assembly and front port plug which are sold separately.



GA-1-1022

[mahle-aftermarket.com](http://mahle-aftermarket.com)